

Old

- \* Drill
- \* Connect through
- \* Fill bores (with special medium)
- \* Brush
- \* Etch

New

- \* Drill
- \* Connect through

\*Etch.....



\*Etch.....




\*Fill bores (with standard medium)...



\*Lacquer...



\*Lacquer .....




\*ISO lacquer...




\*ISO lacquer .....



\*Carbon.....



\*Carbon.....



\*Test

\*Test

\*Mill

\*Mill